L Number	Hits		DB	Time stamp
-	186663	crack\$3 crevice\$1 fissure\$1 fracture\$1	USPAT	2002/02/22 14:21
-	601238	bond\$3 pad\$1	USPAT	2002/02/22 14:47
-	498739	(trench\$2 groove\$1 opening\$1 crevice\$1	USPAT	2002/02/22 15:03
		manger\$1) near10 (lay\$1out lay\$3 arrang\$5		
		position\$3 locat\$4)		
-	71862	(bond\$3 pad\$1) and (crack\$3 crevice\$1	USPAT	2002/02/22 14:48
		fissure\$1 fracture\$1)		2002, 02, 22 11.10
-	11263		USPAT	2002/02/22 14:53
		fissure\$1 fracture\$1)) and ((trench\$2		2002, 02, 22 21.03
		<pre>groove\$1 opening\$1 crevice\$1 manger\$1)</pre>		
		near10 (lay\$4 arrang\$5 position\$3		
		locat\$4))		
-	54674	257/\$.ccls.	USPAT	2002/02/22 14:55
-	44983	438/\$.ccls.	USPAT	2002/02/22 14:55
-	10840	216/\$.ccls.	USPAT	2002/02/22 14:55
-	1416	(257/\$.ccls. 438/\$.ccls. 216/\$.ccls.)	USPAT	2002/02/22 14:56
		and (((bond\$3 pad\$1) and (crack\$3		2002, 02, 22 21,00
		crevice\$1 fissure\$1 fracture\$1)) and		
		((trench\$2 groove\$1 opening\$1 crevice\$1		
		manger\$1) near10 (lay\$4 arrang\$5		
		position\$3 locat\$4)))		
-	751		USPAT	2002/02/22 14:59
		and (((bond\$3 pad\$1) and (crack\$3		2002, 02, 22 21103
		crevice\$1 fissure\$1 fracture\$1)) and		
		((trench\$2 groove\$1 opening\$1 crevice\$1		
1		manger\$1) near10 (lay\$4 arrang\$5		
		position\$3 locat\$4)))) and (cell\$1		
		island\$1 zone\$1 area\$1 region\$1) and		
		stress		
-	290	(((257/\$.ccls. 438/\$.ccls. 216/\$.ccls.)	USPAT	2002/02/22 15:04
		and (((bond\$3 pad\$1) and (crack\$3		
		crevice\$1 fissure\$1 fracture\$1)) and		
		((trench\$2 groove\$1 opening\$1 crevice\$1		
		manger\$1) near10 (lay\$4 arrang\$5		
		position\$3 locat\$4)))) and (cell\$1		
		island\$1 zone\$1 area\$1 region\$1) and		
		stress) and((trench\$2 groove\$1 opening\$1		1
		<pre>crevice\$1 manger\$1) near10 (bond\$3 pad\$1))</pre>		